



HILLSBOROUGH TOWNSHIP BOARD OF EDUCATION

379 South Branch Road • Hillsborough • NJ • 08844-3443 • (908) 431-6600 • www.hillsboroughnj.org

June 22, 2017

Dear Hillsborough High School Community,

As you are aware from the communication on May 5, 2017, in compliance with the Department of Education regulations, Hillsborough High School's drinking water was tested for lead on April 23, 2017.

Following the original testing that occurred, 70 additional outlets were tested on June 12, 2017. The table below identifies the additional water outlets that tested above the lead action level established by the US Environmental Protection Agency for lead in drinking water (15 µg/l [ppb]). This information has also been updated on the district website and the testing information for Hillsborough High School may be viewed [here](#).

Sample Location	First Draw Result in µg/l (ppb)	Remedial Action
Room 127B, Classroom Faucet ID #HHS-1-H127B-ART-CF1-P	16.8	Posted signage "Out of service," automatic sanitizer dispensers implemented, conducting retest.
Room 607, Classroom Faucet ID # HHS-2-H607-CF8-P	34.8	Posted signage "Out of service," automatic sanitizer dispensers implemented, conducting retest.
Room 610, Classroom Faucet ID # HHS-2-H610-CF1-P	43.3	Posted signage "Out of service," automatic sanitizer dispensers implemented, conducting retest.
Room 612, Classroom Faucet ID # HHS-2-H612-CF5-P	26	Posted signage "Out of service," automatic sanitizer dispensers implemented, conducting retest.
Room 624, Classroom Faucet ID # HHS-2-H624-CF1-P	24.6	Posted signage "Out of service," automatic sanitizer dispensers implemented, conducting retest.
Room 627, Classroom Faucet ID # HHS-2-H627-CF1-P	62.5	Posted signage "Out of service," automatic sanitizer dispensers



HILLSBOROUGH TOWNSHIP BOARD OF EDUCATION

379 South Branch Road • Hillsborough • NJ • 08844-3443 • (908) 431-6600 • www.https.us

		implemented, conducting retest.
Room 804, Counter Faucet ID # HHS-2-H804-CF7-P	28	Posted signage “Out of service,” automatic sanitizer dispensers implemented, conducting retest.
Room 804, Counter Faucet ID # HHS-2-H804-CF8-P	275	Posted signage “Out of service,” automatic sanitizer dispensers implemented, conducting retest.
Room 804, Counter Faucet ID # HHS-2-H804-CF9-P	147	Posted signage “Out of service,” automatic sanitizer dispensers implemented, conducting retest.

We appreciate your understanding as we conduct the remediation process for the outlets that were identified at Hillsborough High School.

Sincerely,
Aiman Mahmoud
School Business Administrator/Board Secretary
Hillsborough Township Public Schools