



HILLSBOROUGH TOWNSHIP BOARD OF EDUCATION

379 South Branch Road • Hillsborough • NJ • 08844-3443 • (908) 431-6600 • www.https.us

June 23, 2017

Dear Hillsborough Middle School Community,

As you are aware from the communication on May 5, 2017, in compliance with the Department of Education regulations, Hillsborough Middle School's drinking water was tested for lead on April 22, 2017.

Following the original testing that occurred, 91 additional outlets were tested on June 12, 2017. The table below identifies the additional water outlets that tested at or above the lead action level established by the US Environmental Protection Agency for lead in drinking water (15 µg/l [ppb]). This information has also been updated on the district website and the testing information for Hillsborough Middle School may be viewed [here](#).

Sample Location	First Draw Result in µg/l (ppb)	Remedial Action
Room A8, Classroom Faucet ID # HMS-1-A8-CF8-P	21.3	Posted signage "Out of service," automatic sanitizer dispensers implemented, conducting retest.
Room A9, Classroom Faucet ID # HMS-1-A9-CF7-P	25.7	Posted signage "Out of service," automatic sanitizer dispensers implemented, conducting retest.
Room B4, Classroom Faucet ID # HMS-1-B4-CF3-P	19.6	Posted signage "Out of service," automatic sanitizer dispensers implemented, conducting retest.
Room C7, Classroom Faucet ID # HMS-1-C7-CF7-P	18.3	Posted signage "Out of service," automatic sanitizer dispensers implemented, conducting retest.
Room C7, Classroom Faucet ID # HMS-1-C7-CF8-P	17.3	Posted signage "Out of service," automatic sanitizer dispensers implemented, conducting retest.
Room C8, Classroom Faucet ID # HMS-1-C8-CF1-P	17	Posted signage "Out of service," automatic sanitizer dispensers



HILLSBOROUGH TOWNSHIP BOARD OF EDUCATION

379 South Branch Road • Hillsborough • NJ • 08844-3443 • (908) 431-6600 • www.hillsboroughnj.org

		implemented, conducting retest.
Room C8, Counter Faucet ID # HMS-1-C8-CF5-P	23.5	Posted signage “Out of service,” automatic sanitizer dispensers implemented, conducting retest.
Room C8, Counter Faucet ID # HMS-1-C8-CF6-P	16.8	Posted signage “Out of service,” automatic sanitizer dispensers implemented, conducting retest.
Room C8, Counter Faucet ID # HMS-1-C8-CF8	14.8	Posted signage “Out of service,” automatic sanitizer dispensers implemented, conducting retest.
Room D13, Counter Faucet ID # HMS-1-D13-CF3-P	17.8	Posted signage “Out of service,” automatic sanitizer dispensers implemented, conducting retest.
Room D13, Counter Faucet ID # HMS-1-D13-CF4-P	18.7	Posted signage “Out of service,” automatic sanitizer dispensers implemented, conducting retest.
Room D13, Counter Faucet ID # HMS-1-D13-CF5-P	21.8	Posted signage “Out of service,” automatic sanitizer dispensers implemented, conducting retest.
Room D13, Counter Faucet ID # HMS-1-D13-CF6-P	20.8	Posted signage “Out of service,” automatic sanitizer dispensers implemented, conducting retest.
Room D14, Counter Faucet ID # HMS-1-D14-CF8-P	18.4	Posted signage “Out of service,” automatic sanitizer dispensers implemented, conducting retest.



HILLSBOROUGH TOWNSHIP BOARD OF EDUCATION

379 South Branch Road • Hillsborough • NJ • 08844-3443 • (908) 431-6600 • www.hillsborough.k12.nj.us

We appreciate your understanding as we conduct the remediation process for the outlets that were identified at Hillsborough Middle School.

Sincerely,
Aiman Mahmoud
School Business Administrator/Board Secretary
Hillsborough Township Public Schools